


5/015/047

TELEFAX

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
PRICE FIELD OFFICE
125 SOUTH 600 WEST, PRICE UTAH 84501

OUR PHONE NUMBER: (435) 636-3600
OUR TELEFAX NUMBER: (435) 636-3657

TO: Attention: Tony Gallegos
Branch/Office: DOGm
Company/Agency: _____
Destination Fax Number: 801-355-3940


FROM: Dean Neffeler

SUBJECT: Gypsum Resources Development

DATE AND TIME: 14 November 2000 10:07

NUMBER OF PAGES, INCLUDING THIS COVER SHEET: 5

COMMENTS: _____



s/015/047

Compliance Inspection
Mining Law AdministrationSerial No.: UTU-68019


3809

Company: Gypsum Resources Development, Inc.Inspection Date: December 31, 1997General Location: Chalk HillsAuthor: Neil A. SimmonsLegal Description: T.19S., R.10E., Section 23Mining Claims: White Cap #8Current Status: Inactive

Noncompliance Items:

Remarks: Nothing has changed since the last inspection, No use has been made of the site.Recommendation: Contact Company Monitor X No Action

Other:

Neil A. Simmons 1-2-98
Signature/Date

S/015/047

Compliance Inspection
Mining Law AdministrationSerial No.: UTU-68019


3809

Company: Gypsum Resources Development, Inc.Inspection Date: November 15, 1997General Location: Chalk HillsAuthor: Neil A. SimmonsLegal Description: T.19S., R.10E., Section 23Mining Claims: White Cap #8Current Status: Inactive

Noncompliance Items:

Remarks: Nothing has changed since the last inspection.Recommendation: Contact Company Monitor X No Action

Other:

Neil A. Simmons 11-18-97
Signature/Date

3/015/047

Compliance Inspection
Mining Law AdministrationSerial No.: UTU-68019


3809

Company: Gypsum Resources Development, Inc.Inspection Date: May 13, 1997General Location: Chalk HillsAuthor: Neil A. SimmonsLegal Description: T.19S., R.10E., Section 23Mining Claims: White Cap #8Current Status: Inactive

Noncompliance Items:

Remarks: Nothing has changed since the last inspection. The grizzleys should be removed.Recommendation: Contact Company Monitor X No Action

Other:

Neil A. Simmons 5-13-97
Signature/Date

9/015/047

Moab District
Price River/San Rafael Resource Area
125 South 600 West
Price, Utah 84501

3809
(UTU-68020)
(UT-066)

Clark Powell
P.O. Box 763
Huntington, Utah 84528

APR - 4 1997

Dear Mr. Powell:

We have received a letter from Curtis Larkin of Gypsum Resources Development, Inc., concerning a change in operator. A change in the operator requires the submission of an amended notice. The 43 Code of Federal Regulations 3809 requires submission of a bond for all new or amended notices as of March 31, 1997. The bonding requirements are \$1,000 per acre or actual reclamation costs, whichever is greater.


There is some doubt as to whether or not the Emery County bond will be recognized, so you may have to acquire additional bonding. If you have any questions, please feel free to contact Dean Nyffeler of my staff at (801) 636-3615.

Sincerely,

PENELOPE J. DUNN


Asst Area Manager

NSimmons:ks:4/3/97
powell.ltr



Ms. M. Larkin

3/015/047

**March 27, 1997**

Dean Nyffeler, Geologist
Bureau of Land Management
125 South 600 West
Price, UT 84501

Dear Mr. Nyffeler:

RE: Gypsum Mines in Emery County

Please be advised that GRD has terminated its lease on the gypsum mineral claims held by Clark Powell and colleges. We have an understanding with Mr. Powell that the current reclamation bond with Emery County will be assigned to him and that Mr. Powell will in turn become the operator of the mine.


As you know, the BLM accepted the terms of the Emery County bond in satisfaction of all reclamation bonding requirements. We expect that such remains the case with this change of operators.

Mr. Clark Powell will be in contact with you or you can contact him at 801-687-9343.

Thank you.

Sincerely,

Curtis R. Larkin
Curtis R. Larkin



RECEIVED
EMERY COUNTY
91 MAR 27 PM 3:35
BUREAU OF LAND MANAGEMENT
DEPARTMENT OF THE INTERIOR